

Short Report



Hotel Zur Kanone for Tautenhain | ©Norman Kestel

Hotel Zur Kanone

Dorfstr. 3
07639 Tautenhain

Tel: +49 (0) 36601 55920
Fax: +49 (0) 36601 559270

info@zur-kanone.de
www.zur-kanone.de

Welcome!

Here you can enjoy hearty culinary delights and genuine hospitality in one of the most traditional houses of the Thuringian timber country! The family-run hotel with restaurant is the perfect place for enjoyment, cordiality and short distances to nature and culture. A cannon actually stands on the premises here - according to tradition, it was left by General Napoleon Bonaparte himself! In the "Jägerzimmer" and in the "Alte Stube", wooden paneling and family photos bear witness to the centuries-old tradition of the country inn.

The good souls of the house are still family members: Jana and Lars Sörgel, in already the seventh generation!

On the menu you will find typical woodland dishes interpreted in a modern way. The cannon garden with lounge terrace invites you to relax.

Overview

- Parking at the level hotel entrance
- Reception and breakfast room on the ground floor
- Playground in the garden and toys in the house

Accessibility at a glance

- Parking at the level hotel entrance
- Reception and breakfast room on the ground floor
- Double room for people with disabilities on the ground floor
- Sanitary room with floor-level shower and a grab bar at the toilet
- other guest rooms accessible via stairs

Information for people with walking difficulties and wheelchair users

We have compiled some **information on accessibility** below. Detailed information can be found in the test report.

- There is a marked parking space for people with disabilities (350 cm x 510 cm). It is 10 m away from the entrance. The surface of the path to the entrance is low-vibration and easy to walk and drive on.
- Exterior paths are at least 160 cm wide and have a maximum longitudinal slope of 4%.
- The entrance/access to the building is step-free.
- All rooms and facilities that can be used and raised for the guest are accessible without steps. Door thresholds are a maximum of 1 cm high.
- Existing passages on corridors and paths as well as in rooms are at least 88 cm wide.
- Doors are at least 83 cm wide.
- The counter/cash register is 113 cm high at the lowest point. There is another, equivalent means of communication while seated.
- There are no accessible tables in the breakfast room.
- The play area is not wheelchair accessible. There is no playground equipment that is wheelchair accessible and usable.
- Assistance dogs may be brought into all relevant areas/rooms of the facility/offerings.

Bedroom room 107 on the first floor (double room):

- The movement areas are:
 - in front of essential furnishings (e.g. cupboards) 500 cm x 105 cm;
 - to the left of the bed 105 cm x 355 cm;
 - to the right of the bed 88 cm x 255 cm.
- The bed is 48 cm high.
- The movement areas in the bathroom are:
 - in front of the sink 109 cm x 133 cm;
 - in front of the WC 133 cm x 143 cm;
 - to the left of the WC 99 cm x 56 cm;
 - to the right of the WC 26 cm x 56 cm.
- There is a grab bar to the left of the WC. It cannot be folded up.
- The washbasin is wheelchair accessible at a height of 67 cm and a depth of less than 30 cm.
- The mirror can be viewed while sitting or standing.
- The shower is accessible without steps and is 101 cm x 94 cm.
- A shower seat is available or can be provided if needed (fixed, foldable, hook-in or mobile and stable).

Information for people with hearing impairments and deaf people

We have compiled some **information on accessibility** below. Detailed information can be found in the test report.

- There is no alarm.
- There is no inductive hearing system.
- There are 8 tables with low ambient noise and bright, glare-free lighting, with no lamps standing or hanging that interfere with the field of vision or eye contact.
- There is at least one freely available power outlet near the bed.
- WLAN is available.

Information for visually impaired and blind people

We have compiled some **information on accessibility** below. Detailed information can be found in the test report.

- The entrance area is visually contrasting to the surroundings.
- There are isolated glass doors that do not have safety markings at a height of 40-70 cm and 120-160 cm.
- There are no obstacles (e.g. objects protruding into rooms or corridors).
- Stairs have handrails on both sides. There is a tactile, but not a visual, contrast between the flooring and the stair risers or risers.
- Controls (e.g., door handles, light switches, emergency call buttons) are tactilely detectable throughout the building and are predominantly visually contrasting.
- Walls or other structural elements can be used for orientation almost everywhere.
- Walkways in corridors/walkways/corridors are visually contrasting to the surroundings almost everywhere.
- Almost all elevated areas that can be used by guests (entrance area, cashier/counter, sleeping rooms, corridors, hallways) are well lit, i.e. bright and glare-free.
- Signage designed in legible lettering.
- Assistance dogs may be brought into all relevant areas/rooms of the facility/offer.

Information for guests with cognitive impairments

We have compiled some **information on accessibility** below. Detailed information can be found in the test report.

- The name or logo of the company/facility is clearly recognizable from the outside.
- The destination of the route is within sight or route signs are at a constantly visible distance or there is an uninterrupted route guidance system.
- The front desk is directly visible from the front door.
- There is a business card with the hotel's address and telephone number visibly displayed at the front desk or in the dormitory.
- Assistance dogs (companion dogs, guide dogs for the blind, etc.) may be brought into all relevant areas/rooms of the establishment/offer.

Information for allergy sufferers and people with food intolerances

We have compiled some **information for allergy sufferers** below. Detailed information can be found in the test report.

Food intolerances

Information on the ingredients of the foodstuffs used (also on request).

Food free of flavor enhancers, gluten, fructose, major allergens and lactose, vegetarian and vegan food: on request.

Comfort for all generations

We have compiled some **information on accessibility** below. Detailed information can be found in the test report.

- There is a general parking area. The surface of the path to the entrance is low-vibration and easy to walk and drive on.
- Exterior paths are at least 160 cm wide and have a maximum longitudinal slope of 4%.
- The entrance/access to the building is step-free.

- All rooms and facilities that can be used and raised for guests are accessible without steps. Door thresholds are a maximum of 1 cm high.
- Existing passages on corridors and paths as well as in rooms are at least 88 cm wide.
- Doors are at least 83 cm wide.
- The counter/cash register is 113 cm high at the lowest point. There is another, equivalent means of communication while seated.
- There is no alarm.
- There is no inductive hearing system.
- There are 8 desks with low ambient noise and bright, glare-free lighting.
- There is at least one freely available power outlet near the bed in the rooms.
- WLAN is available.
- The entrance area is visually contrasting to the surroundings.
- There are occasional glass doors that do not have safety markings at a height of 40-70 cm and 120-160 cm.
- There are no obstacles (e.g. objects protruding into rooms or corridors).
- Stairs have handrails on both sides. There is no visual contrast between the flooring and the stair risers or risers.
- Controls (e.g., door handles, light switches, emergency call buttons) are visually contrasting throughout most of the building.
- The walkways in hallways/walkways/corridors are visually contrasting to the surroundings almost everywhere.
- Almost all elevated areas that can be used by guests (entrance area, checkout/counter, dormitories, hallways, corridors) are well lit, i.e., bright and glare-free.
- Signage designed in legible lettering.
- Name or logo of the establishment/facility is clearly visible from the outside.
- Destination of path is within sight or wayfinding signs are at a constantly visible distance or an uninterrupted wayfinding system is in place.
- The front desk is directly visible from the front door.
- There is a business card with the hotel's address and phone number visibly displayed at the front desk or in the dorm room.
- Possibility to store medicines in a cool place.
- Possibility to prepare meals individually according to the quantity needed.

Dormitory room 107 on the first floor (double room):

- The movement areas are:
 - in front of essential furnishings (e.g. cupboards) 500 cm x 105 cm;
 - to the left of the bed 105 cm x 355 cm;
 - to the right of the bed 88 cm x 255 cm.
- The bed is 48 cm high.

- The movement areas in the bathroom are:
- in front of the sink 109 cm x 133 cm;
- in front of the WC 133 cm x 143 cm;
- to the left of the WC 99 cm x 56 cm;
- to the right of the WC 26 cm x 56 cm.
- There is a grab bar to the left of the WC. It cannot be folded up.
- The shower is accessible without steps and is 101 cm x 94 cm.
- There is a shower seat or it can be provided if needed (fixed, foldable, hook-in or mobile and stable).

Image Gallery

We have put together some photos from the company / offer for you. You can find more photos in the detailed reports.



Car park and hotel entrance

©Norman Kestel



Route from car park to hotel entrance

©Sylvia Engel



Bus stop

©Norman Kestel



Image of hotel entrance

©Norman Kestel



Breakfast room on the ground floor

©Norman Kestel



Breakfast room on the ground floor

©Norman Kestel



Image of Bedroom 107 on the ground floor

©Norman Kestel



Sanitary room room 107 for people with disabilities

©Norman Kestel



Playground in the garden

©Norman Kestel