

## Short Report



Peasant War Museum - Korn Market Church (Barfüßerkirche) | ©Sylvia Engel

## Bauernkriegsmuseum - Kornmarktkirche (Barfüßerkirche)

Kornmarkt  
99974 Mühlhausen

Tel: +49 (0) 3601 85660  
Fax: +49 (0) 3601 856626

info@muehlhaeuser-museen.de  
[www.muehlhaeuser-museen.de](http://www.muehlhaeuser-museen.de)

### Welcome!

The former Franciscan monastery church "St. Crucis" is one of the most important preserved mendicant churches in Germany. Since 1975, it has been used as a museum as well as a concert and conference venue. A permanent exhibition informs about the time of the early reformation and the Peasants' War. Another exhibition focuses on the eventful building history of the former church. In addition, a monastery garden laid out according to medieval models and a lapidarium with components of historical buildings invite visitors to linger.



City map Old Town  
Mulhouse

©Sylvia Engel

## Overview

- Church with exhibition and concert hall in the church nave in the middle of Mühlhausen's historic old town.
- Entrance and side entrance to the church
- Ticket office and exhibition with listening stations on one level
- Guided tours, audio guides and app on the World Heritage region are offered

## Accessibility at a glance

- Church with exhibition and concert hall in the church nave in the middle of Mühlhausen's historic old town.
- Entrance with steps and level side entrance to the church
- Ticket office and exhibition with listening stations on one level
- Guided tours, audio guides and app on the World Heritage region are offered
- Changing room and toilet without handholds over 3 steps available

# Information for people with walking difficulties and wheelchair users

We have compiled some **information on accessibility** below. Detailed information can be found in the test report at the end of the text.

- There is no parking space in the vicinity. Exterior paths are at least 500 cm wide.
- Access to the church through the main entrance (3 steps of 5 cm each) or the side entrance (threshold: 3 cm). Ring bell at main entrance to alert service personnel.
- All rooms and facilities that can be used and raised for the guest are accessible without steps.
- Doors are at least 89 cm wide.
- Passages in the church are at least 120 cm wide.
- Exhibits are predominantly visible, perceptible or recognizable while seated.
- Exhibit information is predominantly legible while seated.
- The cash desk is 110 cm high at the lowest point. There is another equivalent communication option available while seated.
- Public toilet accessible via a maximum of one step with a door width of min. 70 cm. Public toilet for people with disabilities next to the tourist information in the Syndikatshof.
- Assistance dogs may be brought into all relevant areas of the church.
- Guided tours are available for people with walking disabilities and wheelchair users. Pre-registration for the tour is required. The entire tour route is accessible to wheelchair users without steps. Mobile or fixed seating is available for people with walking disabilities to use during the tour.

# Information for people with hearing impairments and deaf people

We have compiled some **information on accessibility** below. Detailed information can be found in the test report at the end of the text.

- There is no inductive hearing system.
- Information is conveyed in writing and acoustically.
- There is an alarm, but without flashing or strobe signal.

# Information for visually impaired and blind people

We have compiled some **information on accessibility** below. Detailed information can be found in the test report at the end of the text.

- The entrance area is visually contrasting to the surroundings.
- Steps at the main entrance do not have visually contrasting edges. There is no handrail. There is no visual contrast between the flooring and the stair risers or risers.
- There are partial glass doors without safety markings at a height of 40-70 cm and 120-160 cm.
- There are no obstacles (e.g. objects protruding into rooms or corridors).
- The main "walkways" in the room are tactilely detectable, but not visually contrasting.
- There is visual contrast between the exhibits and the environment.
- Exhibits are generally well lit.
- Exhibit signage is visually contrasting.
- Information is conveyed in writing and acoustically. The following technical means of conveying information are available: Apps available, QR code available, audio guide.
- Assistance dogs may be brought into all relevant areas of the church.

# Information for guests with cognitive impairments

We have compiled some **information on accessibility** below. Detailed information can be found in the test report at the end of the text.

- The name or logo of the establishment/facility is clearly recognizable from the outside.
- The cash register is directly visible from the entrance door or the route to it is marked pictorially and without interruption.
- Information is conveyed in writing and acoustically.
- The following technical options for conveying information are available: Apps, QR code, audio guide.
- Guided tours are offered for people with cognitive impairments, but not in plain language.
- Assistance dogs may be brought into all relevant areas of the church.


# Comfort for all generations

We have compiled some **information on accessibility** below. Detailed information can be found in the test report at the end of the text.

- There is no parking space in the vicinity. Exterior paths are at least 500 cm wide.
- Access to the church via the main entrance (3 steps of 5 cm each) or the side entrance (threshold: 3 cm). Ring bell at main entrance to alert service personnel. The entrance area is visually contrasting with the surroundings. Steps at the main entrance do not have visually contrasting edges. There is no handrail. There is no visual contrast between the flooring and the stair risers or risers.
- The name or logo of the establishment/facility is clearly visible from the outside.
- All rooms and facilities that can be used and elevated by guests are accessible without steps.
- Doorways are at least 89 inches wide.
- Passages in the church are at least 120 cm wide.
- The cash register is directly visible from the entrance door or the path to it is marked pictorially and without interruption.
- The cash register is 110 cm high at the lowest point. There is another, equivalent communication option available while seated.
- There is no inductive hearing system available.
- There are partially glass doors without safety markings at a height of 40-70 cm and 120-160 cm.
- There are no obstacles (e.g. objects protruding into rooms or corridors).
- The main "walkways" in the room are not visually contrasted.
- There is visual contrast between the exhibits and the surroundings.
- Exhibits are generally well lit.
- Exhibit signage is visually contrasting.
- Information is conveyed in writing and acoustically. The following technical means of conveying information are available: Apps available, QR code available, audio guide.
- There is an alarm, but without a flashing or strobe signal.
- Public WC accessible via a maximum of one step with a door width of min. 70 cm.
- Guided tours for people with walking disabilities are available. It is necessary to pre-register for the guided tour. The entire route of the guided tour step-free. Mobile or fixed seating is available for use during the tour.


# Image Gallery

We have put together some photos from the company / offer for you. You can find more photos in the detailed reports.




Way to main and side entrance

©Sylvia Engel




Main entrance with step and bell for service staff

©Sylvia Engel



Side entrance ground level

©Sylvia Engel




Exhibition in the church nave

©Sylvia Engel



Exhibition in the church nave

©Sylvia Engel



Exhibition in the church nave - texts on history

©Sylvia Engel



Exhibition in the church nave

©Sylvia Engel



Exhibition in the church nave - Audio stations

©Sylvia Engel



Exhibition in the church nave - seating area

©Sylvia Engel



Exhibition in the church nave - Exhibits in glass showcases

©Sylvia Engel